HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Sandy Lake Dam, Tender's Residence Sandy Lake Dam Site At Junction of Mississippi River and Sandy River Aitkin County Minnesota

HABS No. MN-126

Documentation:

7 exterior photos (1991) 3 interior photos (1991)

1 photographic copy of historic photo (1937)

11 data pages (1991)

Burt Levy, Photographer, June, 1991

MN-126-1	GENERAL VIEW OF HOUSE, VIEW TO NORTHWEST
MN-126-2	VIEW OF EAST FRONT
MN-126-3	VIEW OF SOUTH SIDE AND SIDE ENTRANCE
MN-126-4	VIEW OF WEST SIDE, BACK ENTRANCE
MN-126-5	VIEW OF NORTH SIDE
MN-126-6	DETAIL OF MAIN ENTRANCE, EAST FRONT
MN-126-7	DETAIL OF SOUTHEAST CORNER, VIEW TO WEST
MN-126-8	LIVING ROOM AND NORTHEAST CORNER ENTRANCE, VIEW TO NORTHEAST
MN-126-9	DINING ROOM AND BEDROOM, VIEW TO THE EAST
MN-126-10	WINDOW TRIM IN NORTHWEST CORNER OF BEDROOM, VIEW TO NORTH
MN-126-11	PHOTOGRAPHIC COPY OF HISTORIC PHOTOGRAPH, 1937, GENERAL VIEW OF HOUSE, LOOKING SOUTHWEST